



realised projects, study



1.) Inspection of the existing pyro process section,

2.) Study with the possibilities for the modernisation,

- **increase of production,**
- **reduction of energy consumption,**
- **reduction of dust emission,**
- **improvement of product quality**



realised projects, study



production [t/d]	rotary kiln [m]
1000 white	Ø 3,80 x 56
1000	Ø 4,00 x 60
1200	Ø 3,00 x 45
1400	Ø 4,15 x 68
1800	Ø 3,35 x 52
2500	Ø 4,35 x 67
2600	Ø 5,00 x 80
3000	Ø 5,60 x 84
3500	Ø 4,40 x 64
4200	Ø 4,60 x 64
4800	Ø 4,80 x 52
5400	Ø 4,55 x 71
7800	Ø 5,60 x 84

realised projects, audit

Audit of the existing cement plant,

- inspection of the plant,
- check the plant conditions,
- find the bottlenecks in case of operation trouble,
- description to remove the bottlenecks.

